

▶ Retail Pricing Information: Wholesale/MSRP

[? Help](#)

Enter Chassis Number (last 7 digits of VIN):

VIN:	WBSHD9316M BK05387	Priority:	9-Performance Center
Prod. No.:	9139060	Customer:	
Status:	Retail	BMW Welt:	
Act. Prod. Date:	7/9/90	Coll. Wk.:	
Model:	9151 M5	Coll. Day/Time:	
Car Type:	STOCK	Salesperson:	
Car Track:		Sub. Srch. Code:	
In-Service Date:		Sub. Notes:	<input type="text"/>
Ind. Block Date:			
Holds:			

Invoiced to:	16800 BROOKS BMW on 8/9/90	Auction/Bid:	N	Price Bl
Invoice:	97616	Wholesale Block:	N	

	Description	Wholesale
Model	9151 M5	USD 46,500
Color	308 Brilliant Red	1
Upholstery	0227 Silver Leather	1
Options	120 M5 GROUP	1
	103 FULL VPC SERVICE CHARGE	1
	943 CD READY RADIO 5/7/8	1
	Net Total	46,560

Price Disclaimer: Total MSRP excludes all taxes, title/documentary fees, registration, tags, BMW center preparation charges, BMW center installed options, insurance, certificate of compliance or non-comp fees, and finance charges. Prices may vary by BMW center.

† Alternate Option

 PRINT

BMW Group - AIR: 2018-12-13 / 07:16
Retailer: 36640/01
Model: M5
Vehicle identification number: WBSHD9316MBK05387
Development code: E34
Model code: HD93
Lead type: HD93

Vehicle

BMW M5, 232KW

WBSHD9316MBK05387



Development code	E34
Colour	brillant-rot
Actual integration level	
Start of warranty	10 August 1990

Technical campaigns

AM__AZ0003: An error occurred when retrieving the central data. Please try again later.

Service contracts

Please check DCSnet Warranty Vehicle Inquiry in DCSnet for available service contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

AM_AZ0001: An error occurred when retrieving the central data. Please contact your ISPI administrator.

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	M5
Body	LIM
Vehicle identification number (last 7-digits)	BK05387
Vehicle identification number (17-digits)	WBSHD9316MBK05387
Development code	E34
Steering	LL
Engine	S38
Engine number	60974829
Transmission	MECH
Transmission number	0003854AOH
Head unit serial number	No head unit could be found
Drive	HECK
Integration level, works	
Production date	12-Jun-1990
Delivery date	11-Jul-1990
National-market version	USA
Paint number	308

Upholstery code 0227

Model code HD93

Basic type HD93

Optional equipment

Optional equipment ex works:

0240 Steering wheel, leather
0458 Electr. front seat adjustment
0640 Preparation f tel.installation universal
0694 Provisions for BMW 6 CD changer
0818 Battery master switch
0925 Dummy-SALAPA
AM__AZ0001: An error occurred when
retrieving the central data. Please contact
your ISPI administrator.

Retrofitted optional equipment:

AM__AZ0001: An error occurred when
retrieving the central data. Please contact
your ISPI administrator.

Control unit software version

Service History

AM__AZ0001: An error occurred when retrieving the central data. Please contact your
ISPI administrator.

Key history (KeyReader)

No key history available.

Warranty history

No warranty history present.

Repair history/customer complaint history

AM__AZ0001: An error occurred when retrieving the central data. Please contact your
ISPI administrator.

Warranty Vehicle Inquiry

Fri Nov 30, 2018 07:30:41 EST

VIN : WBSHD9316MBK05387 CONFIDENTIAL

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES'

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2018 BMW of North America, LLC

Vehicle Data	
VIN: WBSHD9316MBK05387	Davis #: N/A
Chassis Number: BK05387	TCU MIN:
Line Make: 01 - BMW Car	Vehicle Production Date: 1990/06
Model Year: 1991	Series: E34
AG Model Code/Desc: HD93 - M5/4	Wholesale Center ID/Loc: 16800-01
NA Model Code/Desc: 9151 - M5	Wholesale Date: 08/09/1990
Motor Type: S38	Retail Center ID/Loc: 16800-01
Exterior Trim Code: 308 - BRILLIANT RED	Retail Date: 08/10/1990
Interior Color Code: 0227 - SILVER LEATHER	In-Service Date: 08/10/1990
MSRP: \$58,450.00	

Campaign Details as of: November 30, 2018 at 07:30:36 AM EST

NO OPEN CAMPAIGNS

Option Information			
Code	Description	Code	Description
0103	FULL VPC SERVICE CHARGE	0120	M5 GROUP
0943	CD READY RADIO 5/7/8		

Customer Information

Name (First/Last):

Address:

Warranty/Maintenance Programs/Contract Services(Administered by BMW NA)

VIN : WBSHD9316MBK05387 CONFIDENTIAL

Type	Warr/Program Codes/Desc	Contract Number/Status	Eff Date	Enroll Date	No Coverage As Of	Exp Age (Mth)	Exp Odometer (Miles)	Current Age (Mth)	Retail Center	Center Name	Vendor Code Used	Contract Holder (First/Last)
	New Vehicle Limited Warranty	0000000 EXPIRED	08/10/1990		08/10/1994	48	50,000	340				
FE	Federal Emissions 8/80 FE 96 MO/80K MLS	0000000 EXPIRED	08/10/1990	08/10/1990	08/10/1998	96	80000	340	16800	BROOKS BMW	00	
CA	California Emissions	Vehicle may qualify for California Emissions Coverage. Please verify if the vehicle was sold or is registered in a California Emissions Covered State (AZ, CA, CT, DE, MA, MD, ME, NJ, NM, NY, OR, PA, RI, VT, WA). Please confirm model year, selling state and current registration of the vehicle and click here to determine coverage.										

Repair History (Claims)											
Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description	
16800	01	578990		131796	08/05/1999		N/A	26,336	0017050100	B170198 Recall Radiator Cap	
16800	01	495190		0	08/16/1994		N/A	25,466	1341014200	Idle regulating valve misfires / malfunction	
16900	01	413420		0	06/21/1993		N/A	24,321	6451131200	Evaporator temperature sensor, front permanent failure	

----- End of Print -----

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.
© 2016 BMW of North America, LLC